



1584 Hadley Avenue N | Oakdale, MN 55128  
651-739-5086 | [www.ci.oakdale.mn.us](http://www.ci.oakdale.mn.us)

## **QUALITY CONTROL (OAKDALE 1601)**

### **PART 1 GENERAL**

#### **1.01 SECTION INCLUDES**

- A. General Quality Control
- B. Workmanship
- C. Manufacturer's Instructions
- D. Manufacturer's Certificates

#### **1.02 RELATED SECTIONS**

- A. Section 1603 – Reference Standards

#### **1.03 QUALITY CONTROL, GENERAL**

- A. Maintain quality control over suppliers, manufacturers, products, services, site conditions, and workmanship, to produce work of specified quality.

#### **1.04 WORKMANSHIP**

- A. Comply with industry standards except when more restrictive tolerances or specified requirements indicate more rigid standards or more precise workmanship.
- B. Perform work by persons qualified to produce workmanship of specified quality.

#### **1.05 MANUFACTURER'S INSTRUCTIONS**

- A. Comply with instructions in full detail, including each step in sequence. Should instructions conflict with Contract Documents, request clarification from Engineer before proceeding.

#### **1.06 MANUFACTURER's CERTIFICATES**

- A. Owner will employ and pay for services of an Independent Testing Laboratory to perform inspections, tests, and other services required by individual Specifications Sections.
- B. Services will be performed in accordance with requirements of governing authorities and with specified standards.

- C. Reports will be submitted to Engineer (in duplicate) giving observations and results of tests, indicating compliance or non-compliance with specified standards and with Contract Documents.
- D. Contractor shall cooperate with Testing Laboratory personnel: furnish tools, samples of materials, design mix, equipment, storage and assistance as requested.

**END OF SECTION**